WSWN-CRT

WSW-UPC

WSW-BX

2WSW-CRT

3WSW-CRT

F-WSW-UPC

2FWSW-CRT

3FWSW-CRT

Cat. No.	Cubic Capacity	Clamps	Dimensions	Additional Features	Packaging
DEVICE BOXES					
WSWN-CRT	18.0	L	3-3/4 in. x 2-1/4 in. x 2-3/4 in.	External nailing	
WSW-UPC					1 unit
WSW-EP					24 units
WSW-VP					6 units
WSW-FC				F-WSW box without foam gasket	
WSWBX		LA			
2WSW-CRT	33.0	L	3-3/4 in. x 4 in. x 2-3/4 in.	2 Gang	
3WSW-CRT	48.0		3-3/4 in. x 5-3/4 in. x 2-3/4 in.	3 Gang	
4-WSW	67.0		3-3/4 in. x 7-1/2 in. x 2-3/4 in.		
DEVICE BOXES - AIRTIGHT					
F-WSW-UPC	18.0	L	3-3/4 in. x 2-1/4 in. x 2-3/4 in.		1 unit
F-WSW-EP					24 units
FWSWBX		LA			
2FWSW-CRT	33.0	L	3-3/4 in. x 4 in. x 2-3/4 in.	2 Gang	
3FWSW-CRT	48.0		3-3/4 in. x 5-3/4 in. x 2-3/4 in.	3 Gang	
4-FWSW	67.0		3-3/4 in. x 7-1/2 in. x 2-3/4 in.		

Usage: L = NMD90 (Loomex, nonmetallic sheathed cable), LA = AC90 (BX, armoured cable)

NuTek®

WOCT-CRT

F-WOCT-UPC

WRD-CRT

Cat. No.	Cubic Capacity	Clamps	Dimensions (Height x Width x Depth)	Packaging
CEILING BOXES				
WOCT-CRT	26.0	L	3-3/4 in. x 4 in. x 2-3/4 in.	1 unit
WOCT-VP				4 units
CEILING BOX - AIRTIGHT				
F-WOCT-UPC	26.0	L	3-3/4 in. x 4 in. x 2-3/4 in.	
RANGE AND DRYER BOX				
WRD-CRT	61.0	L	4-7/8 in. x 4-7/8 in. x 3 in.	
RANGE AND DRYER BOX - AIRTIGHT				
FWRD-CRT	61.0	L	4-7/8 in. x 4-7/8 in. x 3 in.	

Usage: L = NMD90 (Loomex, nonmetallic sheathed cable)